

## **NOTES:**

- 1. ALL HYDRANT CONNECTIONS MUST BE FIELD INSPECTED, BY A CITY INSPECTOR, PRIOR TO BACKFILLING.
- 2. ALL PIPE BETWEEN TEE AND FIRE HYDRANT SHALL BE DUCTILE IRON CLASS 52. VALVE SHALL BE RODDED TO SERVICE TEE. VALVE AND HYDRANT SHALL HAVE MEGALUGS OR APPROVED EQUAL.

DATE: 03/07	CITY OF NORFOLK — DEPARTMENT OF UTILITIES STANDARD DETAILS	SCALE: NOT TO SCALE
	FIRE HYDRANT CONNECTION	DRAWING NO.  CW 05